

Information Sheet IS24005

GV Series: Using the System Health Eligibility Evaluation Program (SHEEP)

Issue 1.1 24 January 2025

Nautel Limited

10089 Peggy's Cove Road, Hackett's Cove, NS, Canada B3Z 3J4 T.877 6 nautel (628835) or +1.902.823.2233 F.+1.902.823.3183 info@nautel.com

U.S. customers please contact:

Nautel Inc.

201 Target Industrial Circle, Bangor ME 04401 T.877 6 nautel (628835) or +1.207.947.8200 F.+1.207.947.3693 info@nautel.com

e-mail: support@nautel.com

www.nautel.com

IS24005: GV Series: Using the System Health Eligibility Evaluation Program (SHEEP)

INFORMATION SHEET

1 INTRODUCTION

Some GV transmitters are unable to complete certain software upgrades due to issues related to entering and exiting bootloader mode at the 'rack' level (see **NOTE** below). This document describes how to use the System Health Eligibility Evaluation Program (SHEEP), which evaluates the transmitter and determines if its rack(s) can be upgraded.

Using SHEEP is the first step in performing higher-level software upgrades, such as flash-free AUI, GV2 compatibility, etc. Transmitters that are eligible for upgrade require one or more Field Modification kits to complete the upgrade. Transmitters that are not immediately eligible for upgrade require a different Field Modification kit to re-program the rack firmware.

NOTE

The term 'rack' refers to an NAPC158* Module Control/Interface PWB in the transmitter. Each module control/interface PWB contains firmware that interfaces between a group of four (4) RF power modules and the transmitter to control and monitor critical signals. GV transmitters contain the following number of module control/interface PWBs, or racks:

GV3.5/5: One rack (two RF power modules)
GV30-N: Three racks
GV7.5/10: One rack
GV15/20: Two racks
GV60: Six racks

1.1 Equipment Affected

This information sheet applies to all GV series transmitters that are using GV SW 5.x.x.

1.3 Responsibility for Implementation

This procedure should be performed by qualified personnel who are familiar with accessing and using the GV series transmitter's remote AUI.

1.4 Scheduling

Perform this procedure at the earliest convenience of transmitter maintenance personnel, and before ordering any associated Field Modification Kit. **NOTE**: The transmitter must be 'off-air' during the evaluation. Off-air time should be less than five (5) minutes.

1.5 Manpower Requirements

Implementing these instructions requires one person for less than 30 minutes.

1.6 Special Tools/Test Equipment

- Local computer for direct connection or network computer with web browser
- CAT5 Ethernet cable, straight-through or crossover
- SHEEP exe file, via web download

1.7 Materials

No special materials are required to complete the procedure.



1.8 Publications Affected

This modification does not affect the transmitter's documentation.

2 USING SHEEP

- (a) Set the transmitter to remote-enabled mode via the local AUI touch screen, controller UI, or remote interface PWB. Refer to the *Operation & Maintenance Manual* for instructions.
- (b) Download the SHEEP executable file (see link below) to a laptop that will have access to the same network used by the GV transmitter.
 - http://www3.nautel.com/pub/Utilities/SystemHealthEligibilityEvaluationProgram.exe
- (c) Run the SHEEP executable file by double-clicking the downloaded file. The screen shown in Figure 1 will display.



Figure 1: SHEEP login screen

(d) Enter the **System Login** parameters for the transmitter's remote AUI, including System/Transmitter (IP) Address, Port (default is 3501), Username (default is Nautel) and Password (default is no password). Click **Login to System**. If the connection is successful, the screen in Figure 2 will display. If the connection is unsuccessful, a connection error message will appear. In this case, verify the system/transmitter IP address and port number in the AUI's **Menu -> User Settings -> Network Setup** screen, re-enter the **System Login** parameters, and try again.







- (e) Observe and record the transmitter's operating status and any existing alarms.
- (f) Set the GV transmitter to its RF Off state.
- (g) Click the **Evaluate System/Transmitter** button to start the evaluation. A prompt may appear to indicate that RF is already off, and that you will need to turn it back on manually when finished. Click **Yes** to continue. If you start the evaluation in an RF On state, the pop-up in Figure 3 will appear indicating that RF will be turned off:




Figure 3: Off Air Warning pop up

- (h) The program will begin evaluating the 'Rack version' and 'Bootloader version' for each rack in the transmitter. This may take up to two minutes. A progress bar will be displayed throughout the evaluation, along with messages indicating the evaluation details.
- (i) When the evaluation is complete, an information prompt will appear to verify that the AUI is not reporting any alarms before attempting to RF on. If any new alarms are present that were not present in step (d), you will need to cycle (off, then on) the transmitter's ac power. Click **OK** on this prompt to view the evaluation results. Figure 4 shows the completion of a successful evaluation, including the rack and bootloader versions for each rack, plus checkmarks to indicate that the racks (and transmitter) are eligible for software upgrade.




Figure 4: SHEEP successful completion screen



(j) If an evaluation discovers an issue with one or more racks, there will be messages like those shown in Figure 5. SHEEP will make several attempts to retry a rack evaluation, before flagging the rack with an issue.




Figure 5: SHEEP unsuccessful progress and completion screen

- (k) If the evaluation was successful, your transmitter is eligible for specific software upgrades. Report this to a Nautel Customer Service representative at <u>support@nautel.com</u> to discuss the Field Modification required to proceed. Note that while GV60 transmitters can run SHEEP, they do not currently support an upgrade to flash-free AUI, GV2 compatibility, etc.
- (I) If the evaluation was not successful, your transmitter is not yet eligible for specific software upgrades. Click the **Reevaluate System/Transmitter** button to perform the software evaluation again. If still unsuccessful, report this to a Nautel Customer Service representative at support@nautel.com to discuss the Field Modification required to reprogram your transmitter's rack firmware.
- (m) Return the transmitter to desired operation.

If you have any questions or require additional assistance, please contact Nautel's Customer Service Department at:

Telephone: 1-902-823-5100 or 1-877-628-8353 (Canada & USA)

Email: support@nautel.com

