



Nautel VR-Link Software Bulletin

VR-Link Series Software 2.9 Release Notes

General Remarks:

VR-Link Series Software Version 2.9 is a Software update suitable for all Nautel VR-Link Series interface units.

This release is considered **CRITICAL** for those who require any bug fixes/improvements identified below. Nautel recommends you upgrade at your earliest convenience, **during your next scheduled site visit**.

For those who do not require any of the bug fixes/improvements identified below or are satisfied with current behaviour, this release is considered **NON-CRITICAL** and Nautel typically does not recommend you upgrade under these circumstances. If you choose to upgrade, Nautel recommends you perform the upgrade during a regularly scheduled site inspection. In the event you require support from Nautel Customer Service, they may require you to perform an upgrade to the latest software release in order to resolve your issue if deemed necessary.

You can download VR-Link Series Software Version 2.9 [here](#).

Software Upgrade procedures can be found in the *VR-Link RCMS Interface Unit Technical Instruction Manual*. Please be sure to review and understand the complete set of instructions prior to beginning your upgrade.

New Features:

- Added SNMP monitoring for Vector NAVTEX transmitters.

Improvements / Enhancements:

None at this time.

Removed / Retired Features:

None at this time.

Bug Fixes:

None at this time.

Known Issues:

None at this time.

Workarounds:

None at this time.

Installation Considerations:

This software update will take approximately 20 minutes. You will have no connection between the VR-Link unit and the Vector system during this time.