General Remarks:

NX Combiner Software Version 4.2.2 is a **SIGNIFICANT** Software update suitable for all Nautel NX Combiners. We recommend upgrading your transmitter(s) to this latest release **ASAP**.

You can download NXC Software Version 4.2.2 here.

Software Upgrade procedures can be found in the *Non-Standard Maintenance* section of your *Operations and Maintenance Manual*. Please be sure to review and understand the complete set of instructions prior to beginning your upgrade.

New Features:

None at this time.

Improvements / Enhancements:

None at this time

Removed / Retired Features:

None at this time.

Bug Fixes:

- Resolved an incompatibility with the latest Adobe FlashPlayer that was causing difficulties logging in.
- The Standby Test button should now respond correctly to mode and RF on/off states.

Installation Considerations:

This Software update will take approximately 30-60 minutes, and may require multiple reboots. You will be OFF AIR during the upgrade process.