



Nautel Exgine Software Release Notes

Exgine Software 2.7.0

General Remarks:

Exgine Software Version 2.7.0 is a Software update suitable for all Nautel Exgines except those configured for use in M50 excitors.

Nautel considers this release necessary only for those who require any of the new features, improvements and/or bug fixes listed below. Nautel recommends upgrading at the next scheduled site visit or at earliest convenience.

You can download Exgine SW 2.7.0 [here](#).

Software Upgrade procedures can be found in ISO8011*, *Exgine Software Upgrade to V2.x*. Please be sure to review and understand the complete set of instructions prior to beginning your upgrade.

Note: Exgine SW 2.6 and above is not compatible with the M50 exciter. If Exgine SW 2.6 or above was installed on the M50 exciter, revert to Exgine SW 2.3 to restore functionality.

New Features:

- HD single-frequency network functionality is now implemented.
 - Contact Nautel Customer Service for more information.
 - **Note:** Do not enable HD single-frequency network functionality before contacting Nautel Customer Service, otherwise HD functionality will be affected.

Known Issues:

- When enabling decoded HD-1 audio in MP3 mode, the audio in the P3 partition may not be received by an HD Radio receiver.

Installation Considerations:

This software update will take approximately 30 minutes. HD transmission will be OFF AIR during the upgrade process.