



# Nautel Software Bulletin

February 20, 2012

## Nautel NV Series V3.2 Release Notes

If you have been advised by our customer service department to upgrade or if you have experienced problems addressed in this software release please proceed with the download.

The most significant improvements with the latest version include:

### Version 3.2.1 – Released February 20<sup>th</sup>:

- Resolves issue observed in Combined NV transmitter controlled by SC1, where the analog power cal factor was not being updated correctly in all cases. This release only affects combined systems operating in IBOC modes.

### Version 3.2 – Released February 7<sup>th</sup>:

Nautel strongly recommends this software update be done ASAP.

- Corrects issue where the exciter RF output would increase significantly for a short burst during a mode change or ac cycle; increasing the risk for PA input damage. It is highly recommended that this software update be installed as soon as possible.

## Nautel Software Bulletin

Recipients of Nautel bulletins will receive information on software updates, product notices and other information affecting users of Nautel equipment.

## Nautel Customer Service

Tel: 1-877-662-8835

Intl: 1-902-823-3900

[support@nautel.com](mailto:support@nautel.com)

[Start an online chat session with Customer Service \(7:30 AM – 7:30 PM EST\)](#)

Follow the link below for the latest files. Files may be safely transferred using flash drives or “copy and paste”.

[NV Series Software V3.2.1](#)

For record keeping purposes please notify customer service via email when software update is complete.