



# Nautel Software Bulletin

February 7, 2012

## Nautel NV Series V3.2 Release Notes

Nautel strongly recommends this software update be done ASAP.

The most significant improvements with this version include:

### Version 3.2 – Released February 7<sup>th</sup>:

- Corrects issue where the exciter RF output would increase significantly for a short burst during a mode change or ac cycle; increasing the risk for PA input damage. It is highly recommended that this software update be installed as soon as possible.

## Nautel Software Bulletin

Recipients of Nautel bulletins will receive information on software updates, product notices and other information affecting users of Nautel equipment.

## Nautel Customer Service

Tel: 1-877-662-8835

Intl: 1-902-823-3900

[support@nautel.com](mailto:support@nautel.com)

[Start an online chat session with Customer Service \(7:30 AM – 7:30 PM EST\)](#)

Follow the link below for the latest files. Files may be safely transferred using flash drives or “copy and paste”.

[NV Series Software V3.2](#)

For record keeping purposes please notify customer service via email when software update is complete.