



# Nautel Software Bulletin

January 09, 2012

## Nautel VS Series V2.1.3 Release Notes

The most significant improvements with this version include:

### Version 2.1.3 – Released January 9<sup>th</sup>

- Added UI menu option to the transmitter that allows the user to reverse the polarity of deviation vs. modulating signal; positive modulating signal yields positive deviation OR positive modulating signal yields negative deviation.  
The option can be found on the VS menus under:  
Main Menu->System Settings->FM Polarity

### Version 2.1.2 – Released November 23<sup>rd</sup>

- Resolved issue where VS menus did not work properly due to a change in the DSP tools.
- 

### Version 2.1.1 – Released November 23<sup>rd</sup>

- Corrected minor bug in the Spectrum Analyzer function where the span and RBW settings were not taking affect while in MPX mode.
- 

### Version 2.1 – Released November 8<sup>th</sup>

- Incorporates NAND memory error correction, so bit errors that occur while loading the OS do not render the control PWB inoperable.

## Nautel Software Bulletin

Recipients of Nautel bulletins will receive information on software updates, product notices and other information affecting users of Nautel equipment.

## Nautel Customer Service

Tel: 1-877-662-8835  
Intl: 1-902-823-3900

[support@nautel.com](mailto:support@nautel.com)

[Start an online chat session with Customer Service \(7:30 AM – 7:30 PM EST\)](#)

Follow the link below for the latest files. Files may be safely transferred using flash drives or “copy and paste”.

[VS Series Software V2.1.3](#)

For record keeping purposes please notify customer service via email when software update is complete.