

## General Remarks:

VS Series Software Version 4.2.6 is a **SIGNIFICANT** Software update suitable for all Nautel VS-Series transmitters. We recommend upgrading your transmitter(s) to this latest release DURING THE NEXT REGULARLY SCHEDULED SITE INSPECTION.

You can download VS Series Software Version 4.2.6 [here](#).

Software Upgrade procedures can be found in the *Non-Standard Maintenance* section of your *Operations and Maintenance Manual*. Please be sure to review and understand the complete set of instructions prior to beginning your upgrade.

## New Features:

None at this time.

## Improvements / Enhancements:

None at this time.

## Bug Fixes:

- Fixes issue in RDS section where UECP handling code was not properly handling byte stuffing.
- Fixes VS1 IPA reliability issue, related to improper timing of RF drive attenuator adjustments.
- Adjusted command signal timing of UG69 power supply at AC on to ensure stable establishment of DC output voltage.

## Installation Considerations:

This Software update will take approximately 30 minutes, and may require multiple reboots. You will be OFF AIR during the upgrade process.