

## **Nautel Software Bulletin**

June 2, 2014

## Nautel GV Series V4.0.2 Release Notes

Nautel strongly recommends that customers upgrade to GV version 4.0.1 or higher as soon as possible.

Improvements with this release include:

Resolved an erroneous Monitor Fan Fail alarm condition.

The most significant improvements with previous versions include: Version 4.0.1 – Released April 14, 2014

- Reduced transmitter output power overshoot behaviour when HD data is lost.
- · Fixed SBC Watchdog Reset function.
- Prevented transmitter output power from overshooting if the Spectrum/Efficiency Optimizer function is disabled after the system has been optimized.

## Nautel Software Bulletin

Recipients of Nautel bulletins will receive information on software updates, product notices and other information affecting users of Nautel equipment.

## Nautel Customer Service

Tel: 1-877-662-8835 Intl: 1-902-823-3900

support@nautel.com

Start an online chat session with Customer Service (7:30 AM – 7:30 PM EST)

Follow the link below for the latest files. Files may be safely transferred using flash drives or "copy and paste"

**GV Series Software V4.0.2** 

For record keeping purposes please notify customer service via email when software update is complete.

support@nautel.com